32-08JUN10 - Appliances for the Juvenile Justice Center

19	BID TABULATION PRICING	Ice Mas		Federal Sup	ply USA	Ford Restaura	int Suppry
4.8.	PRICING	Make & Model	Extended Price	Make & Model Vulcan 60SS-6B-	Extended Price	Make & Model Vulcan 60SS-6B-	Extended Pri
4.8.1.	Range, 60" Restaurant, Gas		\$	24G	\$3,853.84	24G	\$3,546.59
4011	2 year limited parts & labor warranty, standard		\$		\$0.00		\$0.00
			s				
4.8.1.2.	Natural gas		<u>\$</u>		\$0.00		\$0.00
4.8.1.3.	1675KIT48 Safety System Moveable Gas Connector Kit, ¾" inside diameter, 48" long, covered with stainless steel braid, coated with blue antimicrobial PVC, 1 SnapFast™ QD, 1 full port valve, (2) 90° elbows, coiled restraining cable with hardware, limited lifetime warranty.		S		\$139.00		\$143.25
	140Q0002 Casters w/Brake; Top Plate 5"; Set of 4		\$		\$340.07		\$156.00
	Installation		*		\$215.00		\$528.00
	Extended Total for Range (4.8.1. through 4.8.1.5.)				\$4,547.91		\$4,373.84
	Cabinet, Mobile Heater/Proofer,				ψı,c mor	Win-Holt NHPL-	<i><i><i>ϕ</i></i> 1,070101</i>
4.8.2.	Reach-In			C519-CFC-4	\$1,767.00	1825-UN	\$1,202.04
4.8.3.	Refrigerator, Reach-in	Hoshizaki CRZA-FA	\$2,965.00	Saturn	\$2,816.00	Victory VR-2	\$2,526.68
4.8.3.1.	115v/60/1-ph w/cord & plug, standard		STD	549R	\$0.00		\$0.00
4.8.3.2.	5-year compressor warranty within the USA, included in equipment price		STD	549R	\$0.00		\$0.00
	WARRANTY UPDATED: Full 2 year parts-labor service warranty within the USA, included in						
4.8.3.3.	equipment price, standard. Door hinging: left door hinged on		STD		\$0.00		\$0.00
4834	left, right door hinged on right. Standard.		STD		\$0.00		\$0.00
	5" casters, standard		STD - 4"		\$0.00		\$0.00
	Extended Total for Refrigerator (4.8.3. through 4.8.3.5.)		\$2,965.00		\$2,816.00		\$2,526.68
	Freezer, Reach-in		\$	Saturn 549F	\$3,286.50	TRUE T-35F	\$3,067.27
4.8.4.1.	Self-contained refrigeration standard		\$		\$0.00		\$0.00
4.8.4.2.	Warranty -5 year compressor (self- contained only), applicable to US and Canada		\$		\$0.00		\$0.00
4.8.4.3.	Warranty – 1 year parts and labor, applicable to US and Canada		\$		\$0.00		\$0.00
4.8.4.4.	Left door hinged left, right door hinged right standard		\$		\$0.00		\$0.00
4.8.4.5.	4" Swivel castors, standard (adds 5" to OA height)		\$		\$0.00		\$0.00
4.8.4.6.	Extended Total for Freezer (4.8.4. through 4.8.4.5.)		\$		\$3,286.50		\$3,067.27
4.8.5.	Milk Dispenser		\$	SilverKing SKMAJ21C3	\$1,676.17	SilverKing SKMAJ2/C4	\$1,399.24
4.8.5.1.	Warranty – 1 year parts & labor, standard		\$		\$0.00		\$0.00
	Warranty – additional 4 year compressor, standard 115v/60/1ph		s s		\$0.00 \$0.00		\$0.00 \$0.00
4.8.5.4.	Extended Total for Milk Dispense (4.8.5. through 4.8.5.3.)		\$		\$1,676.17		\$1,399.24
4.8.6.	Dishwasher, Undercounter (Note: County will not accept Hobart brand dishwasher)		\$		\$3,404.39	Insinger RL-30	\$3,285.21

10	BID TABULATION	Ice Mas	ters	Federal Sup	ply USA	Ford Restaura	nt Supply
4.8.	PRICING	Make & Model	Extended Price	Make & Model	Extended Price	Make & Model	Extended Price
		Make de Moder		Make de Moder		Make de Moder	
4.8.6.2.	208-240/60/1, 18-20 amps Installation: Pick-up, deliver,		<u>\$</u>		\$0.00		\$0.00
	uncrate, set in place and install						
4.8.6.3.	new unit.		\$		\$215.00		\$308.00
1961	Extended Total for Dishwasher (4.8.6. through 4.8.6.3.)		s		\$3,619.39		\$3,593.21
4.0.0.4.	(4.8.0. through 4.8.0.3.)	Hoshizaki	φ		\$3,019.39		\$3,393.21
4.8.7.	Ice Maker With Bin, Cube-Style	KM61BAH	\$1,450.00	Manitowac Qm-30a	\$1,552.81	Manitowoc QM-30A	\$1,408.18
4.8.7.1.	3 year parts & labor warranty		STD		\$0.00		\$0.00
4.8.7.2.	115v/60/1ph, standard		STD		\$0.00		\$0.00
4873	3M Valve-In-Head Water Filter System w/Gauge, single vessel, for sediment, chlorine taste & odor, cyst, scale, 0.5 micron rating, 1.5 gallons per minute (5.7 lpm) flow rate, 9,000 gal (34,069 lit) capacity, for ice machines.	ICE-125-8	\$139.70		\$167.88	ICE120-S	\$137.05
4.0.7.5.	Installation: Pick up, deliver,	101-125-5	\$155.70		\$107.00	ICEI20-0	\$157.05
4871	uncrate, set in place and install new unit.		\$300.00		\$215.00		\$374.00
	Extended Total for Ice Maker (4.8.7. through 4.8.7.4.)		\$1,889.70		\$215.00 \$1,935.69		\$1,919.23
488	Food Mixer		s		\$1,214.00	Globe SP8	\$1,139.04
7.0.0.	2 year parts (excludes		¥		ψ1,217.00	0.000.01.0	91,107.0 4
4.8.8.1.	wear/expendable parts), 1 year labor warranty		\$		\$0.00		\$0.00
4.8.8.2.	115/60/1, 5 amp		s		\$0.00		\$0.00
4.8.8.3.	Extended Total for Food Mixer (4.8.8. through 4.8.8.2.).		\$		\$1,214.00		\$1,139.04
4.8.9.	Cart, Food Transport		\$		\$1,512.77	Cambro MDC1418S20-180	\$1,446.98
	SUB-TOTAL (4.8.1.6 + 4.8.2. + 4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. +						
4.9.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.)	\$		\$22,375	.43	\$20,667	.53
4.9.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. +			\$22,375	.43	\$20,667	.53
	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver k	King, Model	s	\$22,375	.43 \$0.00	\$20,667	-\$40.00
	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver K SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26° X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631	King, Model K 17" X 31", Metro Model C175-	<u>s</u>	\$22,375		\$20,667	_
4.10.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SAB196728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet:	King, Model K 17" X 31", Metro Model C175-		\$22,375	\$0.00	\$20,667	-\$40.00
	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Ste	King, Model K 17" X 31", Metro Model C175- cel	S	\$22,375		\$20,667	_
4.10.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver K SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Profer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Ste Trade-In- Refrigerator: McCall M	King, Model K 17" X 31", Metro Model C175- cel		\$22,375	\$0.00	\$20,667	-\$40.00
4.10.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver H SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Profer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Ste Trade-In- Refrigerator: McCall M	King, Model K 17" X 31", Metro Model C175- eel fodel 4=4045, S/N nless Steel	s	\$22,375	\$0.00	\$20,667	-\$40.00
4.10.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981	King, Model K 17" X 31", Metro Model C175- eel fodel 4=4045, S/N nless Steel	s	\$22,375	\$0.00	\$20,667	-\$40.00
4.10. 4.11. 4.12.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981	King, Model (17" X 31", Metro Model C175- cel fodel 4=4045, S/N nless Steel lel UF30K-1410, S/N	\$ \$	\$22,375	\$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611	King, Model (17" X 31", Metro Model C175- cel 40del 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT-	s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str 103322, 55" X 37" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainless	King, Model (17" X 31", Metro Model C175- cel 40del 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel	\$ \$	\$22,375	\$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611	King, Model (17" X 31", Metro Model C175- cel 40del 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel	s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver K SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall N 103322, 55" X 33" X 84, Stai Trade-In- Refrigerator: McCall N 103322, 55" X 33" X 84, Stai Trade-In- Refrigerator: McCall N 103322, 55" X 33" X 84, Stai Trade-In- Berezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainless Trade-In- Range: Vilcan Model 64	King, Model (17" X 31", Metro Model C175- cel 40del 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel	s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13. 4.14. 4.15.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless St Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84. Stai Trade-In- Freezer: Northland Mot D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainles Trade-In- Range: Vilcan Model 60 8861193, Gas , 63" X 31" X 59"	King, Model K 17" X 31", Metro Model C175- zel Addel 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel DFL77R, S/N	s s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13. 4.14. 4.15. 4.16.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainless Trade-In- Range: Vilcan Model 66 8861193, Gas, 63" X 31" X 59" Black SUB-TOTAL OF TRADE-INS (6)	King, Model K 17" X 31", Metro Model C175- zel Addel 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel DFL77R, S/N	s s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13. 4.14. 4.15. 4.16. 4.17.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainles Trade-In- Range: Vilcan Model 66 8861193, Gas, 63" X 31" X 59" Black SUB-TOTAL OF TRADE-INS (c GRAND TOTAL (4.9. less 4.16.)	King, Model K 17" X 31", Metro Model C175- zel Addel 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel DFL77R, S/N	s s s s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$22,375.43	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 \$240.00 \$240.00 \$20,427.53
4.10. 4.11. 4.12. 4.13. 4.14. 4.15. 4.16. 4.17.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver F SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless Str Trade-In- Refrigerator: McCall M 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainless Trade-In- Range: Vilcan Model 66 8861193, Gas, 63" X 31" X 59" Black SUB-TOTAL OF TRADE-INS (6)	King, Model K 17" X 31", Metro Model C175- zel Addel 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel DFL77R, S/N	s s s	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00
4.10. 4.11. 4.12. 4.13. 4.14. 4.15. 4.16. 4.17.	4.8.3.6. + 4.8.4.6. + 4.8.5.4. + 4.8.6.4. + 4.8.7.5. + 4.8.8.3. + 4.8.9.) Trade-In- Milk Dispenser: Silver K SK10MAJ, S/N SABJ96728A Double 5 gal dispenser , 26" X Stainless Steel Trade-In- Heater/Proofer Cabinet: HM2000, S/N H20W-23631 24" X 32" X 70", Stainless St Trade-In- Refrigerator: McCall N 103322, 55" X 33" X 84, Stai Trade-In- Refrigerator: McCall N 103322, 55" X 33" X 84, Stai Trade-In- Freezer: Northland Moc D28-866981 35" X 31" X 76", White Trade-In- Dishwasher: Moyer Die 70, S/N W5611 24" X 26" X 33 3/4", Stainless Trade-In- Range: Vilcan Model 66 8861193, Gas , 63" X 31" X 59" Black SUB-TOTAL OF TRADE-INS (c GRAND TOTAL (4.9. less 4.16.) COOP?	King, Model K 17" X 31", Metro Model C175- zel Addel 4=4045, S/N nless Steel lel UF30K-1410, S/N bell Model 501HT- s Steel DFL77R, S/N	\$\$ \$\$ \$\$ \$\$ \$\$ Yes 30 days	\$22,375	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$22,375.43 Yes	\$20,667	-\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 -\$40.00 \$20,427.53 Yes

<u>No Bids</u> Columbia Appliance