

08-04FEB14 - North Facility Roof Repair

| BID TABULATION | | | G&R Construction, Inc. | Reynolds Construction Company | Weathercraft, Inc. | Meyer Roofing | Watkins Roofing | Missouri Builders Service, Inc. |
|----------------|---|-----|------------------------|-------------------------------|--------------------|---------------|-----------------|---------------------------------|
| 4.7. | PRICING | QTY | UNIT PRICE | UNIT PRICE | UNIT PRICE | UNIT PRICE | UNIT PRICE | UNIT PRICE |
| 4.7.1. | Roof Repair Method 1 as specified in Section 2.1.7. (INSURANCE SPECS) | 1 | \$19,197.00 | \$19,400.00 | \$22,810.00 | \$24,318.00 | \$24,440.00 | \$27,681.00 |

| BID TABULATION | | | Meyer Roofing | G&R Construction, Inc. | Weathercraft, Inc. | Missouri Builders Service, Inc. | Reynolds Construction Company | Watkins Roofing |
|----------------|--|-----|---------------|------------------------|--------------------|---------------------------------|-------------------------------|-----------------|
| 4.7. | PRICING | QTY | UNIT PRICE | UNIT PRICE | UNIT PRICE | UNIT PRICE | UNIT PRICE | UNIT PRICE |
| 4.7.2. | Roof Repair Method 2 as specified in Section 2.1.8. (COUNTY SPECS) | 1 | \$11,900.00 | \$16,048.00 | \$16,365.00 | \$17,563.00 | \$18,501.99 | \$18,826.00 |