

27-24SEP25 - Guardrail - New Installation and Repair Services			BIDDER:	
			James H Drew Corporation	CSD Environmental Services, Inc.
Line #	Description	UOM	Unit	Unit
1	Mobilization	EA	\$1,150.00	\$7,200.00
2	Type A Guardrail			
2.1	Repair - Remove and replace 12.5 foot beam	EA	\$348.30	\$486.00
2.2	Repair - Remove and replace 12.5 foot radius beam, concave or convex	EA	\$567.00	\$1,050.00
2.3	Repair - Remove and replace 6-foot steel post	EA	\$172.54	\$237.00
2.4	Repair - Remove and replace 7-foot steel post	EA	\$210.60	\$267.00
2.5	Repair - Remove and replace 6-foot wood post	EA	\$194.40	\$222.00
2.6	Repair -Realign and use existing post	EA	\$59.00	\$200.00
2.7	Repair - Remove and replace 8-inch x 6-inch x 14-inch wood block	EA	\$42.94	\$63.00
2.8	Repair - Remove and replace end section	EA	\$105.00	\$429.00
2.9	Repair - Remove and replace terminal connector	EA	\$200.00	\$345.00
2.10	Repair -Install post in solid rock or through concrete	EA	\$316.00	\$820.00
3	Type E Guardrail			
3.1	Repair - Remove and replace 12.5 foot thrie beam rail	EA	\$397.00	\$1,455.00
3.2	Repair - Remove and replace 6 foot wood post	EA	\$194.40	\$222.00
3.3	Repair -Realign and use existing post	EA	\$56.70	\$200.00
3.4	Repair -Remove and replace 8-inch x 6-inch x 21-inch wood block	EA	\$56.70	\$78.50
3.5	Repair -Remove and replace three beam terminal connector	EA	\$235.00	\$1,120.00
3.6	Repair -Install post in solid rock or through concrete	EA	\$315.90	\$1,050.00
4	End Terminal			
4.1	New Installation - Type A crashworthy end terminal	EA	\$5,073.00	\$8,874.00
4.2	Repair - Remove and replace type A crashworthy end terminal	EA	\$5,670.00	\$9,474.00
4.3	New installation- Type A flared crashworthy end terminal	EA	\$6,510.00	\$7,095.00
4.4	Repair- Remove and replace Type A flared crashworthy end terminal	EA	\$6,900.00	\$8,000.00
4.5	New installation - Type B crashworthy end terminal	EA	\$11,200.00	\$15,474.00
4.6	Repair - Remove and replace type C crashworthy end terminal	EA	\$28,000.00	\$40,000.00
4.7	Repair - Remove and replace type W beam end section	EA	\$49,000.00	\$1,390.00
5	Anchor			
5.1	Repair - Remove and replace end anchor	EA	\$2,430.00	\$4,170.00
5.2	Repair - Remove and replace embedded guardrail anchor	EA	\$3,850.00	\$6,651.00
5.3	Repair - Remove and replace three beam bridge anchor section	EA	\$5,600.00	\$8,184.00
6	Transition Section			
6.1	Repair - Remove and replace transition section	EA	\$1,053.00	\$10,125.00
6.2	Repair - Remove and replace 6-foot post	EA	\$178.20	\$237.00
6.3	Repair - Remove and replace 7-foot post	EA	\$200.00	\$267.00
7	SRT-350			
7.1	Repair - Remove and replace 6-inch x 8-inch x 45-inch wood post 1-2	EA	\$285.00	\$1,254.00
7.2	Repair - Remove and replace 6-inch x 8-inch x 72-inch wood post 3-9	EA	\$365.00	\$993.00
7.3	Repair - Remove and replace 6-inch x 8-inch x 14-inch wood block	EA	\$44.55	\$63.00
7.4	Repair - Remove and replace strut assembly	EA	\$200.00	\$684.00
7.5	Repair - Remove and replace first slotted 12.5 ft guardrail panel	EA	\$412.80	\$750.00
7.6	Repair - Remove and replace second slotted 12.5 ft guardrail panel	EA	\$412.80	\$650.00
7.7	Repair - Remove and replace barrier end nose piece	EA	\$360.00	\$1,065.00
7.8	Repair - Remove and replace steel foundation tube with soil plate	EA	\$490.00	\$1,122.00
8	Terminal End Marker			
8.1	New Installation - Type III black and yellow object marker on end terminal	EA	\$64.00	\$150.00
8.2	Repair - Install type III black and yellow object marker on end terminal	EA	\$64.00	\$200.00

9 Renewals - Indicate the maximum increase for each potential renewal period			
9.1 1st Renewal period	EA		
9.2 2ndRenewal period	EA		
		\$132,983.83	\$142,316.50

NO BID: Pyles HVAC